

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	2/12/2019	Time:	10:16 AM		
Name of School Corporation:	M.S.D. MARTINSVILLE SCHOOLS			Corp ID:	555925		
Address of School Corporation:	PO Box 1416						
City:	Martinsville	Zip:	46151	County Number:	55		
VIN:	4DRBUC8N4FB638386		License Number:	8820	Bus Number:	49	
Make of Body:	IC Corporation	Year:	2014	Make of Chassis:	IC Corporation	Year:	2015
Bus Type:	C			Mileage:	65214		
Inspection Status:	O	Inspected By:	Mark Raper	PE:	6473		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
67-1-2	Rims are bent or loose
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment
51-2-1	The service door does not open or close properly
55-2-6	Steering box is loose on the frame
55-2-3	Any steering component jams or inhibits safe movement

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.