

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Annual                      **Date:** 2/13/2019 **Time:** 10:37 AM  
**Name of School Corporation:** SOUTHWESTERN JEFFERSON CO SCH CORP **Corp ID:** 394000  
**Address of School Corporation:** 239 Main St  
**City:** Hanover              **Zip:** 47243                      **County Number:** 39  
**VIN:** 1GBJG316681210844              **License Number:** 77528              **Bus Number:** R3  
**Make of Body:** Chevrolet **Year:** 2008              **Make of Chassis:** Chevrolet **Year:** 2008  
**Bus Type:** B                      **Mileage:** 73824  
**Inspection Status:** A                      **Inspected By:** Troy Boyd                      **PE:** 5171

### Violations - Rejected

Inspection Code Description

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**