

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|--------------------------------|------------------------|----------------|-------------------------|--------------------------|
| Type of Inspection: | Post-Crash Inspection | Date: | 2/13/2019 | Time: | 10:15 AM |
| Name of School Corporation: | EVANSVILLE-VANDERBURGH SCH COR | Corp ID: | 827995 | | |
| Address of School Corporation: | 951 Walnut St | | | | |
| City: | Evansville | Zip: | 47713 | County Number: | 82 |
| VIN: | 4UZABRDK08CZ15175 | License Number: | B111L | Bus Number: | C62 |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2007 | Make of Chassis: | Thomas Built Buses, Inc. |
| Bus Type: | C | Mileage: | 122560 | | |
| Inspection Status: | O | Inspected By: | Bradley Miller | PE: | 7809 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 43-1-8 | Any required lettering is missing or faded. |
| 61-1-5 | See Notes: Any defect inspector deems a violation not listed |
| 70-1-12 | See Notes: Any defect inspector deems a violation not listed |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 24-2-1 | There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)). |
| 61-2-1 | There is no brake/king pin certification form, the certification is expired or is not signed within the six-month requirement |

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.