REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual		**Date:** 2/15/2019	**Time:**	10:06 AM
Name of School Corporation:	JOHN GLENN SCHOOL CORPORATION			**Corp ID:**	717150
Address of School Corporation:	101 John Glen Dr				
City:	Walkerton	**Zip:**	46574	**County Number:**	71
VIN:	4UZ6CJAA7XCA36161		**License Number:** 72446	**Bus Number:**	34
Make of Body:	Blue Bird Corporation	**Year:** 1999	**Make of Chassis:** Freightliner	**Year:**	1999
Bus Type:			**Mileage:** 128712		
Inspection Status:	R	**Inspected By:**	Travis Harrold	**PE:**	8022

Violations - Rejected

Inspection Code	Description
29-1-2	Floor covering is missing, cut, loose, buckled, bulging, or not secure
46-1-1	Any seat is loose from the floor or seat rail

Violations - Out of Service

Inspection Code	Description

Bus Type Description