## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Post-Crash Inspection **Date:** 2/21/2019 **Time:** 6:25 PM **Name of School Corporation:** MOORESVILLE CONS. SCHOOL CORP. **Corp ID:** 555930

Address of School Corporation: 173 Indianapolis Rd

City:MooresvilleZip:46158County Number:55VIN:1HA3GSBG1JN002192License Number:58012Bus Number:005Make of Body:StarcraftYear:2018Make of Chassis:ChevroletYear:2018

Bus Type: Mileage: 3895

Inspection Status: O Inspected By: Mark Raper PE: 6473

**Violations - Rejected** 

**Inspection Code Description** 

**Violations - Out of Service** 

Inspection Code Description

There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

**Bus Type Description**