REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection			**Date:**	2/25/2019	**Time:**	11:07 AM
Name of School Corporation:		CLOVERDALE COMMUNITY SCHOOLS				**Corp ID:**	676750
Address of School Corporation:		310 E Logan St					
City:	Cloverdale	**Zip:**	46120			**County Number:**	67
VIN:	4UZABRDT8DCBS8710			**License Number:**	3617	**Bus Number:**	9
Make of Body:	Thomas Built Buses, Inc.	**Year:**	2012	**Make of Chassis:**	Thomas Built Buses, Inc.	**Year:**	2013
Bus Type:	C			**Mileage:**	67628		
Inspection Status:	O	**Inspected By:**	Byron Goodman			**PE:**	7008

Violations - Rejected

Inspection Code	Description
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)

Violations - Out of Service

Inspection Code	Description
41-2-1	Interior is excessively dirty. (Excessive trash or dirt that would jeopardize the safety of students)
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.