REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:2/26/2019Time:9:29 AMName of School Corporation:NORTH LAWRENCE COMM. SCHOOLSCorp ID:475075

Address of School Corporation: 595 Stars Blvd

City:BedfordZip:47421County Number:47VIN:4DRBUAAL7DB311992License Number:5031Bus Number:A44Make of Body:IC Corporation Year:2012Make of Chassis:IC Corporation Year:2013

Bus Type: C Mileage: 132751

Inspection Status: R Inspected By: Travis Coryea PE: 5892

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

64-1-4 Any front turn signal does not function properly

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.