

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	2/26/2019	Time:	11:38 AM		
Name of School Corporation:	VIGO COUNTY SCHOOL CORPORATION			Corp ID:	848030		
Address of School Corporation:	3250 Maple Ave						
City:	Terre Haute	Zip:	47804	County Number:	84		
VIN:	4DRBWAAR1GB111824		License Number:	10031	Bus Number:	1546	
Make of Body:	IC Corporation	Year:	2015	Make of Chassis:	IC Corporation	Year:	2016
Bus Type:	D			Mileage:	32959		
Inspection Status:	O	Inspected By:	Byron Goodman	PE:	7008		

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-2	Any body surface protrudes beyond the normal limits of the body structure
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.