REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:2/27/2019Time:8:37 AMName of School Corporation:CENTER GROVE COMM. SCHOOL CORPCorp ID:414205

Address of School Corporation: 4900 W Stones Crossing Rd

City:GreenwoodZip:46143County Number:41VIN:1GBJG316091149654License Number:80385Bus Number:208Make of Body:IC Corporation Year:2009
Make of Chassis:
IC Corporation Year:
2009

Bus Type: Mileage: 55601

Inspection Status: A Inspected By: John Pang PE: 6196

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description