

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 2/27/2019	<b>Time:</b> 9:00 AM
<b>Name of School Corporation:</b> CENTER GROVE COMM. SCHOOL CORP	<b>Corp ID:</b> 414205	
<b>Address of School Corporation:</b> 4900 W Stones Crossing Rd		
<b>City:</b> Greenwood	<b>Zip:</b> 46143	<b>County Number:</b> 41
<b>VIN:</b> 1GBJG312461237339	<b>License Number:</b> 84276	<b>Bus Number:</b> 204
<b>Make of Body:</b> Mid Bus, Inc.	<b>Year:</b> 2007	<b>Make of Chassis:</b> Chevrolet
<b>Year:</b> 2007	<b>Bus Type:</b>	<b>Mileage:</b> 43809
<b>Inspection Status:</b> A	<b>Inspected By:</b> John Pang	<b>PE:</b> 6196

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

<u>Bus Type</u>	<u>Description</u>
-----------------	--------------------