

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 3/11/2019	<b>Time:</b> 10:11 AM
<b>Name of School Corporation:</b> MARION COMMUNITY SCHOOLS	<b>Corp ID:</b> 272865	
<b>Address of School Corporation:</b> 826 E 30th St		
<b>City:</b> Marion	<b>Zip:</b> 46952	<b>County Number:</b> 27
<b>VIN:</b> 1BAKJCPA4CF285514	<b>License Number:</b> 2385	<b>Bus Number:</b> 20
<b>Make of Body:</b> Blue Bird Corporation	<b>Year:</b> 2011	<b>Make of Chassis:</b> Blue Bird Corporation
<b>Year:</b> 2012	<b>Mileage:</b> 99861	<b>PE:</b> 7018
<b>Bus Type:</b> C	<b>Inspected By:</b> Randy McPike	
<b>Inspection Status:</b> O		

### Violations - Rejected

#### Inspection Code Description

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).
50-2-1	There is no seat belt cutter in the vehicle

#### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**