REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspec	tion		Date:	3/8/2019	Time:	11:45 AM
Name of School	•			IUNITY SCHOO	LS	Corp ID:	202270
Address of Scho	ool Corporation:	ť	59040 Minut	eman way			
City:	Elkhart	Z	Zip:	46517		County Number:	20
VIN:	1BABNBPA5HF33	4872		License Number:	14152	Bus Number:	19
Make of Body:	Blue Bird Corporation	Year: 2	2016	Make of Chassis:	Blue Bird Corporation	Year:	2017
Bus Type:	D			Mileage:	28976		
Inspection Status:	0	_	Inspected By:	Wes Rowlader		PE:	7427

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code	Description
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.