

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 3/12/2019	Time: 10:19 AM
Name of School Corporation: MARION COMMUNITY SCHOOLS	Corp ID: 272865	
Address of School Corporation: 826 E 30th St		
City: Marion	Zip: 46952	County Number: 27
VIN: 4DRBUC8N8HB232100	License Number: 10547	Bus Number: 97
Make of Body: IC Corporation	Year: 2015	Make of Chassis: IC Corporation
Bus Type: C	Mileage: 36332	Year: 2017
Inspection Status: R	Inspected By: Randy McPike	PE: 7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
50-1-3	The seat belt cutter is contained in a compartment.
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.