

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	3/12/2019	Time:	10:31 AM		
Name of School Corporation:	MARION COMMUNITY SCHOOLS			Corp ID:	272865		
Address of School Corporation:	826 E 30th St						
City:	Marion	Zip:	46952	County Number:	27		
VIN:	4DRBUC8N1HB232102		License Number:	10546	Bus Number:	99	
Make of Body:	IC Corporation	Year:	2015	Make of Chassis:	IC Corporation	Year:	2017
Bus Type:	C			Mileage:	26391		
Inspection Status:	R	Inspected By:	Randy McPike	PE:	7018		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.