REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	3/13/2019	**Time:**	11:04 AM
Name of School Corporation:	BLACKFORD COUNTY SCHOOLS			**Corp ID:**	50515
Address of School Corporation:	668 W CR 200S				
City:	Hartford City	**Zip:**	47348	**County Number:**	5
VIN:	4DRBUAANXEB417565	**License Number:**	10158	**Bus Number:**	115
Make of Body:	IC Corporation **Year:** 2012	**Make of Chassis:**	IC Corporation	**Year:**	2014
Bus Type:	C	**Mileage:**	53179		
Inspection Status:	O	**Inspected By:**	Jamie Hotchkiss	**PE:**	6458

Violations - Rejected

Inspection Code	Description
63-1-4	Any rear tire has less than 2/32 inch tread depth when measured in any two adjacent major grooves

Violations - Out of Service

Inspection Code	Description
63-2-1	Tires are cut, weathered, cracked, have lumps, or breaks that expose the cord

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.