REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		Date:	3/13/2019	Time:	11:04 AM
Name of School Co	orporation: BLA	CKFORD COUN	TY SCHOOLS		Corp ID:	50515
Address of School	Corporation:	668 W CR 200	S			
City:	Hartford City	Zip:	47348		County Number:	5
VIN:	4DRBUAANXEB417	7565	License Number:	10158	Bus Number:	115
Make of Body:	IC Corporation Year	: 2012	Make of Chassis:	IC Corporation	Year:	2014
Bus Type:	С		Mileage:	53179		
Inspection Status:	0	Inspected By:	Jamie Hotchkiss		PE:	6458

Violations - Rejected

Inspection Code	Description
63-1-4	Any rear tire has less than 2/32 inch tread depth when measured in any two adjacent major grooves

Violations - Out of Service

Inspection CodeDescription63-2-1Tires are cut, weathered, cracked, have lumps, or breaks that expose the cord

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.