

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	3/8/2019	<b>Time:</b>	11:22 AM
<b>Name of School Corporation:</b>	NETTLE CREEK SCHOOL CORP.			<b>Corp ID:</b>	898305
<b>Address of School Corporation:</b>	795 Baker Rd				
<b>City:</b>	Hagerstown	<b>Zip:</b>	47346	<b>County Number:</b>	89
<b>VIN:</b>	1HVBABP92A940304	<b>License Number:</b>	18525	<b>Bus Number:</b>	15
<b>Make of Body:</b>	IC Corporation	<b>Year:</b>	2001	<b>Make of Chassis:</b>	IC Corporation
<b>Year:</b>	2001	<b>Year:</b>	2001	<b>Year:</b>	2001
<b>Bus Type:</b>	C	<b>Mileage:</b>	159537	<b>PE:</b>	8139
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Jeremy Mason	<b>PE:</b>	8139

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
50-1-1	The seat belt cutter is not located within the driver's view and reach
50-1-2	The seat belt cutter is not secured using a positive fastening method.
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
29-1-2	Floor covering is missing, cut, loose, buckled, bulging, or not secure

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**