

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection	Date: 3/19/2019	Time: 9:50 AM
Name of School Corporation: CLINTON PRAIRIE SCHOOL CORP.	Corp ID: 121160	
Address of School Corporation: 4431 W SR 28		
City: Frankfort	Zip: 46041	County Number: 12
VIN: 4DRBUSKN9DB154052	License Number: 3120	Bus Number: 10
Make of Body: IC Corporation	Year: 2012	Make of Chassis: IC Corporation
Year: 2013	Mileage: 72182	PE: 7421
Bus Type: C	Inspected By: Nate King	
Inspection Status: O		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
62-1-1	Any lens is cracked, missing, faded or of the wrong color
62-1-2	One (1) taillight or one (1) brake light does not function
23-1-5	Any hanger, clamp or bracket is missing, loose or broken
23-1-6	Tailpipe does not extend to, or extends more than 1" beyond the perimeter of the bus body

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.