

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 3/19/2019 **Time:** 9:50 AM
Name of School Corporation: CLINTON PRAIRIE SCHOOL CORP. **Corp ID:** 121160
Address of School Corporation: 4431 W SR 28
City: Frankfort **Zip:** 46041 **County Number:** 12
VIN: 4DRBUSKN9DB154052 **License Number:** 3120 **Bus Number:** 10
Make of Body: IC Corporation **Year:** 2012 **Make of Chassis:** IC Corporation **Year:** 2013
Bus Type: C **Mileage:** 72182
Inspection Status: O **Inspected By:** Nate King **PE:** 7421

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
62-1-1	Any lens is cracked, missing, faded or of the wrong color
62-1-2	One (1) taillight or one (1) brake light does not function
23-1-5	Any hanger, clamp or bracket is missing, loose or broken
23-1-6	Tailpipe does not extend to, or extends more than 1" beyond the perimeter of the bus body

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.