

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                                |                        |                      |                         |                         |      |
|---------------------------------------|--------------------------------|------------------------|----------------------|-------------------------|-------------------------|------|
| <b>Type of Inspection:</b>            | Post-Crash Inspection          | <b>Date:</b>           | 3/19/2019            | <b>Time:</b>            | 1:33 PM                 |      |
| <b>Name of School Corporation:</b>    | WESTERN IN COMM ACTION PROGRAM | <b>Corp ID:</b>        | 84001Z               |                         |                         |      |
| <b>Address of School Corporation:</b> | PO Box 1018                    |                        |                      |                         |                         |      |
| <b>City:</b>                          | Terre Haute                    | <b>Zip:</b>            | 47807                | <b>County Number:</b>   | 84                      |      |
| <b>VIN:</b>                           | 1GBJG31K291175251              | <b>License Number:</b> | 1175251              | <b>Bus Number:</b>      | 2                       |      |
| <b>Make of Body:</b>                  | Chevrolet                      | <b>Year:</b>           | 2009                 | <b>Make of Chassis:</b> | Collins Bus Corporation |      |
| <b>Year:</b>                          | 2009                           |                        | <b>Mileage:</b>      | 71853                   |                         |      |
| <b>Bus Type:</b>                      | A2                             |                        | <b>Inspected By:</b> | Byron Goodman           | <b>PE:</b>              | 7008 |
| <b>Inspection Status:</b>             | O                              |                        |                      |                         |                         |      |

### Violations - Rejected

#### Inspection Code Description

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u>  |
|------------------------|---|
| 63-2-3                 | Any tire is flat  |
| 63-2-1                 | Tires are cut, weathered, cracked, have lumps, or breaks that expose the cord   |
| 24-2-1                 | There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)). |

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.