

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|--------------------------------|------------------------------|------------------|-------------|--------------------------|------------|
| Type of Inspection: | Post-Crash Inspection | Date: | 3/25/2019 | Time: | 10:00 AM |
| Name of School Corporation: | FORT WAYNE COMMUNITY SCHOOLS | | | Corp ID: | 20235 |
| Address of School Corporation: | | | | | |
| City: | Zip: | County Number: 2 | | | |
| VIN: | 1T8819D2XH1109988 | License Number: | 11792 | Bus Number: | 237 |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2016 | Thomas Built Buses, Inc. | Year: 2017 |
| Bus Type: | D | Mileage: | 56200 | | |
| Inspection Status: | O | Inspected By: | Eric Egbert | PE: | 7006 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 24-1-2 | The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails |
| 34-1-1 | Any headlight is inoperative |
| 64-1-1 | Turn signals are not properly mounted |
| 11-1-1 | The front bumper does not extend to the edge of the fenders |
| 67-1-2 | Rims are bent or loose |
| 25-1-1 | Mirror or mirror backs that are loose or improperly mounted |
| 70-1-3 | There are any breaks, nicks or chips larger than 3/4 inch in diameter in the area covered by the wipers on the drivers' side |
| 33-1-2 | The grill is missing |
| 68-1-1 | Washers do not function properly in any manner |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
| 63-2-3 | Any tire is flat |

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.