REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:**	3/26/2019	**Time:**	8:19 AM
Name of School Corporation:	LAKE CENTRAL SCHOOL CORP.				**Corp ID:**	454615
Address of School Corporation:	8855 Wicker Ave					
City:	St John	**Zip:**	46373		**County Number:**	45
VIN:	4DRBUC8N6HB413616		**License Number:**	10660	**Bus Number:**	19
Make of Body:	IC Corporation	**Year:** 2015	**Make of Chassis:**	IC Corporation	**Year:**	2017
Bus Type:	C		**Mileage:**	36629		
Inspection Status:	R	**Inspected By:**	Nathan Sherer		**PE:**	7029

Violations - Rejected

Inspection Code	Description
50-1-1	The seat belt cutter is not located within the driver's view and reach

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.