

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	3/21/2019	Time:	11:40 AM
Name of School Corporation:	NORTH LAWRENCE COMM. SCHOOLS			Corp ID:	475075
Address of School Corporation:	595 Stars Blvd				
City:	Bedford	Zip:	47421	County Number:	47
VIN:	4DRBUAAN1DB311987			License Number:	5032
Make of Body:	IC Corporation	Year:	2012	Make of Chassis:	IC Corporation
Bus Type:	C	Mileage:	48140	Year:	2013
Inspection Status:	O	Inspected By:	Travis Coryea	PE:	5892

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.