

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 4/1/2019 Time: 8:01 AM  
Name of School Corporation: HANOVER COMM. SCHOOL CORP. Corp ID: 454580  
Address of School Corporation: PO Box 645  
City: Cedar Lake Zip: 46303 County Number: 45  
VIN: 1GB3B2BG3C1195996 License Number: 014189 Bus Number: 43  
Make of Body: Star Trans Year: 2012 Make of Chassis: Chevrolet Year: 2012  
Bus Type: Mileage: 36132  
Inspection Status: O Inspected By: Tim Grayson PE: 7558

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-5	Any hanger, clamp or bracket is missing, loose or broken

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
8-2-1	There is no brake certification, or the certification has expired or is not signed

### Bus Type Description