REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		Date:	4/1/2019	Time:	8:01 AM
Name of School Corporation: HANOVER COMM. SCHOOL CORP.					Corp ID:	454580
Address of School	Corporation:	PO Box 645				
City:	Cedar Lake	Zip:	46303		County Number:	45
VIN:	1GB3B2BG3C1	195996	License Number:	014189	Bus Number:	43
Make of Body:	Star Trans Year	: 2012	Make of Chassis:	Chevrolet	Year:	2012
Bus Type:			Mileage:	36132		
Inspection Status:	0	Inspected By:	Tim Grayson		PE:	7558

Violations - Rejected

Inspection CodeDescription23-1-5Any hanger, clamp or bracket is missing, loose or broken

Violations - Out of Service

Inspection CodeDescription8-2-1There is no brake certification, or the certification has expired or is not signed

Bus Type Description