## **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection: Annual			Date:	4/1/2019	Time:	8:51 AM
Name of School Corporation:		HANOVER COMM. S	SCHOOL CORP.		Corp ID:	454580
Address of School	Corporation:	PO Box 645				
City:	Cedar Lake	Zip:	46303		<b>County Number:</b>	45
VIN:	4DRBUAAN68E	3499587	License Number:	4952	Bus Number:	8
Make of Body:	IC Corporation	Year: 2007	Make of Chassis:	IC Corporation	Year:	2008
Bus Type:	С		Mileage:	94451		
Inspection Status:	0	Inspected By:	Tim Grayson		PE:	7558

**Violations - Rejected** 

Inspection Code	<u>Description</u>
23-1-5	Any hanger, clamp or bracket is missing, loose or broken
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative

## Violations - Out of Service

Inspection Code	<b>Description</b>
65-2-1	Warning lights fail to operate correctly
59-2-4	Stop arm does not function properly

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.