

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Re-Inspection      **Date:** 4/1/2019      **Time:** 9:19 AM  
**Name of School Corporation:** HANOVER COMM. SCHOOL CORP.      **Corp ID:** 454580  
**Address of School Corporation:** 14525 Wicker  
**City:** Cedar Lake      **Zip:** 46303      **County Number:** 45  
**VIN:** 1GB3B2BG3C1195996      **License Number:** 014189      **Bus Number:** 43  
**Make of Body:** Star Trans      **Year:** 2012      **Make of Chassis:** Chevrolet      **Year:** 2012  
**Bus Type:**      **Mileage:** 36132  
**Inspection Status:** R      **Inspected By:** Tim Grayson      **PE:** 7558

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>                                       |
|------------------------|--|
| 23-1-5                 | Any hanger, clamp or bracket is missing, loose or broken |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

| <u>Bus Type</u> | <u>Description</u> |
|-----------------|--------------------|
|-----------------|--------------------|