# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Annual | | **Date:** | 3/29/2019 | **Time:** | 10:10 AM |
| **Name of School Corporation:** | BARTHOLOMEW CONS. SCHOOL CORP. | | | | **Corp ID:** | 30365 |
| **Address of School Corporation:** | 1260 N Marr Rd | | | | | |
| **City:** | Columbus | **Zip:** | 47201 | | **County Number:** | 3 |
| **VIN:** | 1GB3G2BG5F1138736 | | **License Number:** | 34017 | **Bus Number:** | W13 |
| **Make of Body:** | Chevrolet **Year:** 2015 | | **Make of Chassis:** | Chevrolet | **Year:** | 2015 |
| **Bus Type:** | | | **Mileage:** | 50945 | | |
| **Inspection Status:** | A | **Inspected By:** | Travis Coryea | | **PE:** | 5892 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|

| Bus Type Description |
|---|