

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 4/2/2019 **Time:** 8:49 AM
Name of School Corporation: DELAWARE COMM. SCHOOL CORP. **Corp ID:** 181875
Address of School Corporation: 7821 SR 3 N
City: Muncie **Zip:** 47303 **County Number:** 18
VIN: 4DRAPSKH29A674247 **License Number:** 715775 **Bus Number:** 2
Make of Body: IC Corporation **Year:** 2007 **Make of Chassis:** IC Corporation **Year:** 2009
Bus Type: **Mileage:** 66303
Inspection Status: O **Inspected By:** Jamie Hotchkiss **PE:** 6458

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 35-1-1 | A heater motor is not operating properly |

Violations - Out of Service

Inspection Code Description

Bus Type Description