

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 4/2/2019	<b>Time:</b> 8:49 AM	
<b>Name of School Corporation:</b> DELAWARE COMM. SCHOOL CORP.	<b>Corp ID:</b> 181875		
<b>Address of School Corporation:</b> 7821 SR 3 N			
<b>City:</b> Muncie	<b>Zip:</b> 47303	<b>County Number:</b> 18	
<b>VIN:</b> 4DRAPSKH29A674247	<b>License Number:</b> 715775	<b>Bus Number:</b> 2	
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2007	<b>Make of Chassis:</b> IC Corporation	<b>Year:</b> 2009
<b>Bus Type:</b>	<b>Mileage:</b> 66303		
<b>Inspection Status:</b> <input type="radio"/>	<b>Inspected By:</b> Jamie Hotchkiss	<b>PE:</b> 6458	

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
35-1-1	A heater motor is not operating properly
62-1-2	One (1) taillight or one (1) brake light does not function

### Violations - Out of Service

Inspection Code Description

Bus Type Description