REPORT OF SCHOOL BUS INSPECTION

Type of 10:05 Annual Time: Date: 4/3/2019 Inspection: AM 787775

Name of School Corporation: SWITZERLAND COUNTY SCHOOL CORP Corp ID:

Address of School Corporation: 1040 W Main St

County City: Vevay Zip: 47043 78 Number:

License VIN: 1BAKGCPA3AF272684 **Bus Number:** 14 Number:

Make of Blue Bird Blue Bird Make of Body: Year: 2010 Year: 2010 Corporation Corporation Chassis:

Bus Type: С Mileage: 98261

Inspection Inspected 0 Chris Clark PE: 6665

Status: By:

Violations - Rejected

Inspection Code	<u>Description</u>
68-1-1	Washers do not function properly in any manner
23-1-9	Tailpipe has been reduced in a size (diameter) from the rear of the muffler
23-1-11	Any tailpipe exits beneath an emergency door
44-1-3	See Notes: Any defect inspector deems a violation not listed
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

Inspection Code	<u>Description</u>
20-2-3	The "anti-vandalism" audible warning device fails to operate
59-2-1	Any stop arm light is inoperative

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.