

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	3/22/2019	Time:	10:13 AM		
Name of School Corporation:	DUGGER UNION COMMUNITY SCHOOLS			Corp ID:	9950		
Address of School Corporation:	7356 E. Co. Rd. 50 S.						
City:	Dugger	Zip:	47848	County Number:	77		
VIN:	4DRBUC8N9FB514176		License Number:	B514176	Bus Number:	3	
Make of Body:	IC Corporation	Year:	2014	Make of Chassis:	IC Corporation	Year:	2015
Bus Type:	C			Mileage:	49799		
Inspection Status:	O	Inspected By:	Byron Goodman	PE:	7008		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
20-1-1	Lettering is missing or improper (Two (2) inch high letters EMERGENCY DOOR directly above the inside and outside of door, and operating instructions on how to open door.)

### Violations - Out of Service

#### Inspection Code Description

#### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.