

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|--------------------------------|------------------------|-----------------|-------------------------|--------------|
| Type of Inspection: | Post-Crash Inspection | Date: | 4/4/2019 | Time: | 2:09 PM |
| Name of School Corporation: | UNION-NORTH UNITED SCHOOL CORP | Corp ID: | 717215 | | |
| Address of School Corporation: | 22601 Tyler Rd | | | | |
| City: | Lakeville | Zip: | 46536 | County Number: | 71 |
| VIN: | 4UZAAXDD75CM96469 | License Number: | temp837388 | Bus Number: | 4 |
| Make of Body: | Freightliner | Year: | 2003 | Make of Chassis: | Freightliner |
| | | Year: | 2005 | | |
| Bus Type: | C | Mileage: | 191310 | | |
| Inspection Status: | O | Inspected By: | Jamie Hotchkiss | PE: | 6458 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 11-1-2 | The front or rear bumper is not properly attached, missing, torn, loose, or altered. |
| 23-1-12 | See Notes: Any defect inspector deems a violation not listed |
| 23-1-5 | Any hanger, clamp or bracket is missing, loose or broken |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 8-2-2 | If the bolts for the brake caliper are loose, missing or broken off |
| 70-2-1 | Any glass or glazing is broken through or missing |

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.