

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	4/8/2019	Time:	1:55 PM
Name of School Corporation:	FORT WAYNE COMMUNITY SCHOOLS			Corp ID:	20235
Address of School Corporation:					
City:	Zip:				
VIN:	1T88Y9D27K1138951	License Number:	22206	Bus Number:	156
Make of Body:	Thomas Built Buses, Inc.	Year:	2018	Thomas Built Buses, Inc.	Year:
Bus Type:	D	Mileage:	11927		2019
Inspection Status:	O	Inspected By:	Eric Egbert	PE:	7006

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
51-1-4	See Notes: Any defect inspector deems a violation not listed
57-1-2	Step-well area is weakened
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
34-1-5	See Notes: Any defect inspector deems a violation not listed
70-1-2	There are intersecting cracks in the windshield area covered by the wipers

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.