

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                            |                        |               |                         |                          |
|---------------------------------------|----------------------------|------------------------|---------------|-------------------------|--------------------------|
| <b>Type of Inspection:</b>            | Annual                     | <b>Date:</b>           | 4/9/2019      | <b>Time:</b>            | 8:35 AM                  |
| <b>Name of School Corporation:</b>    | MITCHELL COMMUNITY SCHOOLS |                        |               | <b>Corp ID:</b>         | 475085                   |
| <b>Address of School Corporation:</b> | 441 N 8th St               |                        |               |                         |                          |
| <b>City:</b>                          | Mitchell                   | <b>Zip:</b>            | 46446         | <b>County Number:</b>   | 47                       |
| <b>VIN:</b>                           | 4uzaaxbw33ck41531          | <b>License Number:</b> | 22new         | <b>Bus Number:</b>      | 22                       |
| <b>Make of Body:</b>                  | Thomas Built Buses, Inc.   | <b>Year:</b>           | 2003          | <b>Make of Chassis:</b> | Thomas Built Buses, Inc. |
| <b>Bus Type:</b>                      | C                          | <b>Mileage:</b>        | 170675        | <b>Year:</b>            | 203                      |
| <b>Inspection Status:</b>             | O                          | <b>Inspected By:</b>   | Travis Coryea | <b>PE:</b>              | 5892                     |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>  |
|------------------------|---|
| 63-1-4                 | Any rear tire has less than 2/32 inch tread depth when measured in any two adjacent major grooves |
| 29-1-2                 | Floor covering is missing, cut, loose, buckled, bulging, or not secure                            |
| 41-1-4                 | There is debris in the bus. (needs cleaned/includes dirt)   |

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**