REPORT OF SCHOOL BUS INSPECTION

Type of Annual Date: 4/10/2019 Time: 10:54 AM

Name of School Corporation: KOKOMO SCHOOL CORPORATION Corp ID: 343500

Address of School Corporation: 620 W Deffenbaugh

 City:
 Kokomo
 Zip:
 46901
 County Number:
 34

 VIN:
 4DRBUC8N9JB578226
 License Number:
 19107
 Bus Number:
 237

Make of Body: IC Corporation Year: 2017 Make of Chassis: IC Corporation Year: 2018

Bus Type: C Mileage: 22193

Inspection Status: R Inspected By: Randy McPike PE: 7018

Violations - Rejected

| Inspection Code | <u>Description</u> |
|-----------------|--|
| 50-1-3 | The seat belt cutter is contained in a compartment. |
| 46-1-2 | Any seat back or bottom is loose |
| 62-1-2 | One (1) taillight or one (1) brake light does not function |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.