REPORT OF SCHOOL BUS INSPECTION

| Type of Inspection: | Annual | | Date: | 4/10/2019 | Time: | 10:33 AM |
|--------------------------------|--------------------------------|------------------|---------------------|----------------------------|-------------------|-------------|
| Name of School Corporation: | LEBANON COMMUNITY SCHOOL CORP. | | | | Corp ID: | 60665 |
| Address of Schoo | I Corporation: | 505 Ransdell | l Rd | | | |
| City: | Lebanon | Zip: | 46052 | | County Number: | 6 |
| VIN: | 1GB3GRBG8H | 1349327 | License Number: | a2 | Bus Number: | 105 |
| Make of Body: | Chevrolet Year | : 2018 | Make of Chassis: | Collins Bus Corporation | Year: | 2017 |
| Bus Type: | В | | Mileage: | 12893 | | |
| Inspection Status | : A | Inspected By: | Jeff Kastenschn | nidt | PE: | 5805 |

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.