### REPORT OF SCHOOL BUS INSPECTION

9:22 Type of 4/11/2019 **Time**: Annual Date: Inspection: AM Name of School Corporation: KOKOMO SCHOOL CORPORATION 343500 Corp ID: **Address of School Corporation:** 620 W Deffenbaugh County City: Kokomo Zip: 46901 34 Number: License VIN: 1GB3G2BG9C1138606 19443 **Bus Number:** 101 Number: Make of Collins Bus Chevrolet Year: Year: 2012 Make of Body: 2012 Corporation Chassis: Bus Type: A2 Mileage: 50347 Inspected PE: **Inspection Status:** O Randy McPike 7018 By:

## Violations - Rejected

# Inspection Code

50-1-2 The seat belt cutter is not secured using a positive fastening method.

69-1-3 Wiper blades are torn, cracked, brittle or otherwise deteriorated

#### **Violations - Out of Service**

Inspection Code	<u>Description</u>
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

**Description** 

#### **Bus Type Description**

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.