# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Annual | | **Date:** | 4/18/2019 | **Time:** | 8:25 AM |
| **Name of School Corporation:** | SOUTH DEARBORN COMM. SCH. CORP | | | | **Corp ID:** | 151600 |
| **Address of School Corporation:** | 6109 Squire Place | | | | | |
| **City:** | Aurora | **Zip:** | 47001 | | **County Number:** | 15 |
| **VIN:** | 1GB3G2BG1B1160016 | | **License Number:** | 7701 | **Bus Number:** | 52 |
| **Make of Body:** | Collins Bus Corporation | **Year:** 2011 | **Make of Chassis:** | Chevrolet | **Year:** | 2011 |
| **Bus Type:** | A2 | | **Mileage:** | 55697 | | |
| **Inspection Status:** | A | **Inspected By:** | Chris Clark | | **PE:** | 6665 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|

**Bus Type Description**

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**