REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	4/22/2019	**Time:**	8:48 AM
Name of School Corporation:	OREGON-DAVIS SCHOOL CORP.			**Corp ID:**	757495
Address of School Corporation:	5998 N 750 E				
City:	Hamlet	**Zip:**	46532	**County Number:**	75
VIN:	4DRBUAAP4EB498743	**License Number:**	5875	**Bus Number:**	19
Make of Body:	IC Corporation **Year:** 2013	**Make of Chassis:**	IC Corporation	**Year:**	2014
Bus Type:	C	**Mileage:**	42386		
Inspection Status:	R	**Inspected By:**	Nathan Sherer	**PE:**	7029

Violations - Rejected

Inspection Code	Description
50-1-1	The seat belt cutter is not located within the driver's view and reach

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.