

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	4/22/2019	<b>Time:</b>	9:26 AM
<b>Name of School Corporation:</b>	OREGON-DAVIS SCHOOL CORP.	<b>Corp ID:</b>	757495		
<b>Address of School Corporation:</b>	5998 N 750 E				
<b>City:</b>	Hamlet	<b>Zip:</b>	46532	<b>County Number:</b>	75
<b>VIN:</b>	1GB3G2BG1B1155785	<b>License Number:</b>	5337	<b>Bus Number:</b>	22
<b>Make of Body:</b>	Collins Bus Corporation	<b>Year:</b>	2011	<b>Make of Chassis:</b>	Chevrolet
<b>Bus Type:</b>	C	<b>Mileage:</b>	72709		
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Nathan Sherer	<b>PE:</b>	7029

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
64-1-5	LED type lights have 25% to 49% of the pixels inoperable in any one light
23-1-6	Tailpipe does not extend to, or extends more than 1" beyond the perimeter of the bus body

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.