

## REPORT OF SCHOOL BUS INSPECTION

|                                                                  |                                   |                              |
|------------------------------------------------------------------|-----------------------------------|------------------------------|
| <b>Type of Inspection:</b> Annual                                | <b>Date:</b> 4/16/2019            | <b>Time:</b> 10:49 AM        |
| <b>Name of School Corporation:</b> SHENANDOAH SCHOOL CORPORATION | <b>Corp ID:</b> 333435            |                              |
| <b>Address of School Corporation:</b> 5100 N Raider Rd           |                                   |                              |
| <b>City:</b> Middletown                                          | <b>Zip:</b> 47356                 | <b>County Number:</b> 33     |
| <b>VIN:</b> 1FDWE35P64HB45775                                    | <b>License Number:</b> 20888      | <b>Bus Number:</b> 27        |
| <b>Make of Body:</b> Thomas Built Buses, Inc.                    | <b>Year:</b> 2005                 | <b>Make of Chassis:</b> Ford |
| <b>Year:</b> 2004                                                | <b>Mileage:</b> 73379             |                              |
| <b>Bus Type:</b> B                                               |                                   |                              |
| <b>Inspection Status:</b> A                                      | <b>Inspected By:</b> Jeremy Mason | <b>PE:</b> 8139              |

### Violations - Rejected

Inspection Code Description

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**