

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	4/17/2019	Time:	9:43 AM
Name of School Corporation:	INTERLOCAL CAP HEAD START			Corp ID:	33002Z
Address of School Corporation: PO Box 449					
City:	New Castle	Zip:	47362	County Number:	33
VIN:	1GB3G2BG7D1125676		B800H	Bus Number:	8
Make of Body:	Chevrolet	Year:	2012	Make of Chassis:	Chevrolet
Bus Type:	A2			Mileage:	23717
Inspection Status:	R	Inspected By:	Jeremy Mason	PE:	8139

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
35-1-1	A heater motor is not operating properly
28-1-1	The first aid or bodily fluid (optional) kit is not in a dustproof, detachable container, has sharp protrusions, or requires tools to open.
79-1-3	If equipped the emergency warning buzzer does not sound
20-1-10	See Notes: Any defect inspector deems a violation not listed
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.