REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	4/24/2019	**Time:**	1:05 PM
Name of School Corporation:	NORTH DAVIESS CO. COMM. SCHOOL			**Corp ID:**	141375
Address of School Corporation:	5494 E SR 58				
City:	Elnora	**Zip:**	47529	**County Number:**	14
VIN:	1FDWE35P55HA51789	**License Number:**	69262	**Bus Number:**	ND5
Make of Body:	Mid Bus, Inc. **Year:** 2005	**Make of Chassis:**	Ford	**Year:**	2005
Bus Type:		**Mileage:**	75070		
Inspection Status:	R	**Inspected By:**	Mike Adams	**PE:**	7407

Violations - Rejected

Inspection Code	Description
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code	Description

Bus Type Description