

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	4/23/2019	<b>Time:</b>	11:02 AM
<b>Name of School Corporation:</b>	ANDERSON COMM. SCHOOL CORP.			<b>Corp ID:</b>	485275
<b>Address of School Corporation:</b>	1600 Hillcrest Ave				
<b>City:</b>	Anderson	<b>Zip:</b>	46011	<b>County Number:</b>	48
<b>VIN:</b>	4UZAAXCS14CM20907	<b>License Number:</b>	B944B	<b>Bus Number:</b>	23
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2003	<b>Make of Chassis:</b>	Freightliner
<b>Bus Type:</b>	C	<b>Year:</b>		<b>Year:</b>	2004
<b>Inspection Status:</b>	O	<b>Mileage:</b>	158098	<b>Inspected By:</b>	Jeremy Mason
		<b>PE:</b>			8139

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
63-1-4	Any rear tire has less than 2/32 inch tread depth when measured in any two adjacent major grooves

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94
63-2-5	Any rear tire has less than 1/32 inch tread depth when measured in any two adjacent major grooves

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.