

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 4/25/2019	<b>Time:</b> 9:55 AM
<b>Name of School Corporation:</b> TWIN LAKES SCHOOL CORPORATION	<b>Corp ID:</b> 918565	
<b>Address of School Corporation:</b>		
<b>City:</b>	<b>Zip:</b>	<b>County Number:</b> 91
<b>VIN:</b> 4DRBUSKP49A119370	<b>License Number:</b> 31408	<b>Bus Number:</b> 15
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2008	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2009	<b>Mileage:</b> 87348	<b>PE:</b> 7421
<b>Bus Type:</b> C	<b>Inspected By:</b> Nate King	
<b>Inspection Status:</b> R		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
53-1-2	Any leaf spring extends more than 1/4 inch beyond the vertical alignment of the spring stack

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**