

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	4/29/2019	<b>Time:</b>	9:47 AM		
<b>Name of School Corporation:</b>	RENSSELAER CENTRAL SCHOOL CORP			<b>Corp ID:</b>	373815		
<b>Address of School Corporation:</b>	900 E Washington						
<b>City:</b>	Rensselaer	<b>Zip:</b>	47978	<b>County Number:</b>	37		
<b>VIN:</b>	1GBJG316X91164744	<b>License Number:</b>	MO76930	<b>Bus Number:</b>	09		
<b>Make of Body:</b>	Collins Bus Corporation	<b>Year:</b>	2009	<b>Make of Chassis:</b>	Chevrolet	<b>Year:</b>	2009
<b>Bus Type:</b>		<b>Mileage:</b>	181677				
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Tim Grayson	<b>PE:</b>	7558		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
34-1-1	Any headlight is inoperative

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description