REPORT OF SCHOOL BUS INSPECTION

| Type of Inspection: | Annual | | | Date: | 4/24/2019 | Time: | 9:08 AM |
|-------------------------------------|--------------------------|------------------|--------|--------------------|--------------------------|-------------------|------------|
| Name of School of Address of School | • | BROWN 0 | | CORP LHOUSE LN | | Corp ID: | 70670 |
| City: | Nashville | Zip: | : | 47448 | | County Number: | 7 |
| VIN: | 1BAKFCPH48F250 |)493 | | License Number: | 13NEW | Bus Number: | 13 |
| Make of Body: | Blue Bird Corporation | Year: 200 | 7 | Make of Chassis: | Blue Bird Corporation | Year: | 2008 |
| Bus Type: | С | | | Mileage: | 133424 | | |
| Inspection Status: | 0 | lnsp By: | pected | Travis Coryea | | PE: | 5892 |

Violations - Rejected

| Inspection Code | <u>Description</u> | | | | |
|--------------------|-----------------------------------------------------------------------------------------------------------|--|--|--|--|
| 64-1-2 | A lens is cracked, missing or wrong color | | | | |
| 65-1-1 | Any lens is cracked, broken or discolored | | | | |
| 57-1-1 | Step covering is loose, buckled, or made of a material other than rubber (i.e. rugs, carpets, mats, etc.) | | | | |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.