

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 5/2/2019	Time: 9:31 AM
Name of School Corporation: OAK HILL UNITED SCHOOL CORP.		Corp ID: 525625
Address of School Corporation: PO Box 550		
City: Converse	Zip: 46919	County Number: 52
VIN: 1BAKGCEA5JF337232	License Number: 14527	Bus Number: 27
Make of Body: Blue Bird Corporation	Year: 2016	Make of Chassis: Blue Bird Corporation
Bus Type: C	Mileage: 31852	Year: 2018
Inspection Status: R	Inspected By: Randy McPike	PE: 7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
57-1-5	Step-well light is missing or inoperative
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.