

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 5/2/2019	Time: 9:53 AM
Name of School Corporation: OAK HILL UNITED SCHOOL CORP.	Corp ID: 525625	
Address of School Corporation: PO Box 550		
City: Converse	Zip: 46919	County Number: 52
VIN: 4UZABRDT2BCAU0751	License Number: 1125	Bus Number: 5
Make of Body: Thomas Built Buses, Inc.	Year: 2009	Make of Chassis: Freightliner
Year: 2010	Mileage: 126777	PE: 7018
Bus Type: C		
Inspection Status: R	Inspected By: Randy McPike	

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
20-1-8	If bus manufactured after 5-2-1994, positive door opening device is missing or fails to operate properly
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.